Date:

Thursday, 04/10/2007 10:38:49 AM

User:

Linda Lacelle

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

Type.

Job Number **Estimate Number**  : 35006

P.O. Number

: 10559

:MA

This Issue

: 04/10/2007 : NC,

Prsht Rev. · MA First Issue : 33541

**Previous Run** Written By

Checked & Approved By

Comment

**Additional Product** 

: Est Rev.E 04.02.16

Est Rev:F 06-03-29

Est Rev:G 06.12.08

Est Rev:H 07-04-30

. 16

S.O. No. : NA

As per Rev D

per ECN 886

LANDING GEAR

Reformat: Added D3189-1 K/DS

Remove Coments on Pick List JLM

**Drawing Name** 

: HIGH AFT X-TUBE 412

Part Number

: D412664203

**Drawing Number** 

: D412-664-243 REV D : N/A

Project Number **Drawing Revision** 

: D :JA

Material Due Date

ЕĈ

JLM

Description:

**ENGINEERING RESOURCE #1** 

: 11/10/2007

Qty:

1 Um:

Oil

SIC

Each

D412-664-203 **DESC** 

Crosstube Aft High B32227

LOT MODEL **Bell 412**  SIC STC SH01-9 SR01298NY

**CHG006** 

MADEUN CANADA

Job Number:



Seq. #:

1.0

1.2.0

3.0

4.0

**Machine Or Operation:** 

**ENGINEERING 1** 

Comment: ENGINEERING RESOURCE #1 **PULL FROM STOCK:** 

1 X D412-664-203 B32227

D412664203

**ENGINEERING 1** 

Comment: Qty.: 1.0000 Each(s)/Unit

Crosstube Aft High

Total:

1.0000 Each(s)

Crosstube Aft High

**ENGINEERING RESOURCE #** 



07/10/04

011004

**Comment: ENGINEERING RESOURCE #1** 

-CYCLE TUBE SEVERAL TIMES UP TO 6000LBS, IN DEFLECTION RIG

-VISUALLY INSPECT WITH MAGNIFYING GLASS FOR ANY CRACKS IN PAINT

-IF CRACKS ARE FOUND, LPI

SPRAY PAINTING

Comment: SPRAY PAINTING

REPRIME/SPRAY PAINT

AS NECESSARY

27 07-10-17

071004

	nursday, 04/10/2007 10:38:49 AM nda Lacelle	Process Sheet	
Custome	r: CU-DAR001 Dart Helicopters S	Services Drawing Name: HIGH AF	T X-TUBE 412
Job Numbe	r: 35006	Part Number: D412664	203
Job Number:			
Seq. #:	Machine Or Operation:	Description	:
5.0	QC14	INSPECT SPRAY PAINT	
Comr	nent: INSPECT SPRAY PAINT PACKAGING 1	PACKAGING RESOURCE #1	
	nent: PACKAGING RESOURCE		
<b>-</b>	ENSURE KIT IS COMPLE		
7.0	RE-PACKAGE PER PPP USING NEW B/N NEW LABELS REQ'D	ACH Y S S/10/	24 6 1/10/24
· · · · · · · · · · · · · · · · · · ·	nent: FINAL INSPECTION/W/O		
Job Completion			11 St. 10.24
Dick			W 84, 10. 1
Clam	p/MS21920-	28 B 104423 X4	
chafing Abrasic	sheld/3189	-1 B30201 x2 856-600 B26650	81 01 TO 18
Clamp	MS21920-3	o B100154 x2	
Robber	cushion/D350	1-506-3510 B351	26 x2
<b>5</b> .2 As:	semble As Pa	er Dwy Rev. D. ml	07 10 18 (1)
QC 5	Inappert Assy	Ja-10.23 (D)	

Form: rprocess

Page 2

### **Jason Murdoch**

From: Mike Petsche [mpetsche@dartaero.com]

Sent: Wednesday, October 03, 2007 4:15 PM

To: Bill Beckett; 'David Shepherd'; 'Mike O'Reilly'; 'Peggy McDonald'; 'Spyke Whiting'; 'Dan Stow';

'Jason Murdoch'

Subject: FW: Crosstubes

With regard to the email from Tim Fox, here is the plan while we are waiting for the parts back from AAI:

Three sample crosstubes have been LPI'ed. One new, (actually a customer return, but never flown) and two crosstubes than have been yielded in previous deflection testing. The yielded parts have only ever been primed. Only one of the yielded parts showed any evidence of possible cracking. They were small cracks perpendicular to the axis of the tube, similar to the ones on the failed Asesa tubes, ("stretchmarks"). The primer will be stripped from this tube and the LPI will be repeated to see if the crack was only in the primer or whether the cracking was in the almuminium. (Again, this tube was a part that was scrapped during deflection testing)

It was also determined that you can't really effectively LPI a tube that has been painted. The LPI on the new tube was inconclusive.

We will now take a new tube out of stock and cycle it several times up to 6000lbs in our deflection rig. It has been determined that this would be a safe load to apply to the crosstube without compromising its life. It will then be removed from the rig and visually inspected with a magnifying glass. Specifically, the paint will be examined to identify any possible cracks in the paint. If we see any cracks in the paint, we will LPI it.

Once we get the parts back from AAI, we will strip the paint in the "areas of concern" and perform LPI.

From there we will decide how to proceed.

# Mike Petsche

Design Manager DART Aerospace ph:613-632-5200 ext. 250 mobile: 514-833-1657

Skype: mike.petsche

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.488 / Virus Database: 269.14.0/1046 - Release Date: 03/10/2007 10:08 AM

No virus found in this outgoing message.

## L Lacelle

From: Dan Stow [dstow@dartaero.com]

**Sent:** October 4, 2007 7:05 AM

To: 'Chantelle Lavoie'; Linda Lacelle (Linda Lacelle)


Cc: Bill Beckett (Bill Beckett)
Subject: D412-664-203 B32227

Please be advised that I have removed a D412-664-203 B32227 from stock so that we can test the affects of cycling on the paint. The crosstube will probably have to be touched up but it will be returned to stock.

Dan Stow Technical Support Dart Aerospace Tel: 613.632.5200


Cell:613.676.0992

dstow@dartaero.com





	DESIG	PH	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
ı	CHECK	ED 🕜	APPROVED	DRAWING NO. REV. D
ı		41		D412-664-243 SHEET 1 OF 3
ľ	DATE			TITLE SCALE
	07.0	3.09		CROSSTUBE ASSEMBLY (412 HI AFT) NTS
	Α	****	01.10.17	NEW ISSUE
	В		05.02.04	ADD HOLES FOR COMPATABILITY WITH BHT/AA SKIDTUBES
	С		06.10.27	REMOVE D2856-600-1087, ADD D2732-058 & MAGNOBOND 6398 MS21920-32 WAS MS21920-30
	D	_	07.03.09	REMOVE D2732-058, CHANGE TO



Qty	Part Number	Description
Х	D412-664-243	CROSSTUBE ASSEMBLY (412 HIGH AFT)
1	D6009-129	CROSSTUBE
2	D3595-063-570	RUBBER CUSHION
1	D2896-1	SUPPORT
2	D2856-600-1009	ABRASION STRIP
4	MS21920-28	CLAMP
2	MS21920-30	CLAMP (OR MS21920-32) 1,
2	D3189-1	CHAFING SHIELD
A/R	MAGNOBOND 6398	ROCKWELL SPECIFICATION RBO-120-023 ADHESIVE (TEXTRON/BELL SPEC. 299-947-100 TYPE II, CLASS 2 ADHESIVE)

#### **GENERAL NOTES:**

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 2) MATERIAL: MANUFACTURED FROM D6009-129 FINISHED LENGTH = 124.09±0.020
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2 PAINT OUTSIDE PER DART 005 4.2
- 4) PART IS SYMMETRIC ABOUT CENTERLINE.
- RUN-OFF PART. BLEND OUT EDGE LONGITUDINALY, TRANSITION SHOULD BE SMOOTH.
- 6) BEND PROGRESSIVELY WITH A MINIMUM OF 8 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 6% BASED ON O.D.
- 7) LIQUID PENETRANT INSPECT OUTSIDE SURFACE OF CROSSTUBE PER QSI 038.
- 8) SCRIBE DART PART NUMBER AND BATCH NUMBER IN THIS AREA WITH VIBRATING STYLLS
- 9) INSTALL D2856-600-1009 ABRASION STRIP WITH A 0.13 (REF) GAP ON BOTTOM SIDE OF CROSSTUBE PER QSI 035.
- 10) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE.
- 11) APPLY A 0.03" TO 0.06" THICK LAYER OF MAGNOBOND 6398 TO THE SURFACE OF D2896-1 THAT WILL BE IN CONTACT WITH THE CROSSTUBE PER QSI 015. LET CURE FOR 12 HOURS AFTER INSTALLATION AND PRIOR TO PACKAGING.
- 12) INSTALL MS21920-30 CLAMPS (OR -32) WITH D3595-063-570 RUBBER CUSHIONS TO SECURE D2896-1 SUPPORT ON TOP SIDE OF THE CROSSTUBE. ENSURE CLAMPS ARE OPPOSITE CROSSTUBE SUPPORT.
- 13) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING.

in/0 35006

Copyright © 2001 by DART AEROSPACE LTD

